

Turners Certified Imports 50 Point Check

Report ID: 17,743,648

Version:

12 Mar 2019 Created:

Note: This report is not a warranty


This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.


Nissan Body Style: Sedan Make: Good Seats: Odometer: 129,098 Kms Skyline Model: Good Carpets: 2007 7AT0DH12X19109364 VIN: Year: Good Panels: **Under Carriage & Under Bonnet Inspection Comments** Tidy. Dashboard: Good **General Comments** Nice tidy car. **Electrical Transmission & Drive Engine Battery** Operation Oil level **Head lights** Noise Smoke & fumes


	·
Engine Timing Mechanism:	Timing Chain
Evidence of Cam Belt Replacement:	Not Applicable
Replaced At (odometer reading):	
Road Conditions During Test Drive:	Dry
	_

depth)









Turners Certified Key	
1	= Pass X = Fail
•	= Not applicable for this vehicle

Inspected by: Daryll Timms Date: 12 Mar 2019