

Report ID: 17,743,871 Version: 1 15 Mar 2019 Created:

Make:	Mazda	Model:	Mazda6	Body Style:	Sedan		Pass	Fail	N/A
Year:	2015	<b>Registration:</b>	JDN321	Reg Expiry:	03 Apr 2019	Engine	1	1	
WoF Expiry:	04 Jun 2019	Odometer:	73,845 Kms	Good No:	17743871	Oil level	~		
VIN:	JM0GJ103200206886	Next Service:		Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	s sc			715	HILS	Operation	~		
PT = paint defe				$\left( \right)$		Noise	~		
C = crack				+		Clutch			~
P = pin dent	HIC				세비	CV joints	~		
* = decals	sc 916			-Jul-	ELD SC	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC SC SC W P						Performance	~		
D. L.L.		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		+
Body insp	pection Comments			, ,	, ,	Tyres (lowest observed tread	-	oftvre	es)
						Left front 3 mm			
						Right front		3	mm
						Left rear		5	mm
Condition		a a ati a a .	\\/			Right rear		-	 mm
Conditions During Body Inspection: Wet						Spare	6 mm Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Tidy	-	•				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		<u> </u>
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Jeals						Tail lights	~		
Carpets	Good						<i>v</i> <i>v</i>		
Danala	Good					Dashboard warning lights	~		┼──┤
Panels						Wipers (front & rear)	v v		
Dashboa	rd Good					Window winder FL	~		┼──┤
	I					Window winder FR	~		┼──┤
General C	<u>Comments</u>					Window winder RL	<i>v</i> <i>v</i>		
						Window winder RL Window winder RR	<i>v</i> <i>v</i>		+
						Rear view mirrors	<i>v</i> <i>v</i>		
						Radio (basic test only)	<i>v</i> <i>v</i>		
						CD (basic test only)	<i>v</i> <i>v</i>		
						Number of keys			
							2		
Road Con	ditions During Test	t Drive:	Wet			Central locking	V 		
Engine Ti	ming Mechanism:	Timing	Chain			Remote locking	V		
-	of Cam Belt Replac	-	lot Applicable	Kms:		Sat. Nav. (basic test only)	V		
						Reversing camera	~		
Inspecte	d by: Stuart Melbourr	ne				Date: 15 Mar 20	19		
· · ·									

I have read and understood this condition guide.

Name: .....

Signature: .....