

Basic Vehicle Condition Guide

Report ID: 17,743,918


Version: 3

Created: 12 Jun 2019

Make: Model: Hyundai 140 **Body Style:** Wagon Year: 2015 Registration: JAU826 Reg Expiry: 27 Jul 2019 WoF Expiry: **Odometer: Good No:** 01 Jan 2020 126,857 Kms 17743918 VIN: KMHLC81UMEU09219 Next Service: 132 000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Front wheel drive

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

	_
General	Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Xinghui Lin 12 Jun 2019 Inspected by: Date:

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	v v		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	3	3	mm
Right front	3		mm
Left rear	Ę	5	mm
Right rear	ï	5	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	V V		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	V V V V V		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	~		

Signature: