

Basic Vehicle Condition Guide

Report ID: 17,744,984

Pass

~

~

/

V

1

V

Tyres (lowest observed tread depth of tyres)

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Right front

Left rear

Right rear

Suspension

Suspension performance Steering performance

Shock absorbers

Spare

Coolant condition Performance

Radiator / Hoses (visual)

Created: 07 Dec 2018

Fail

N/A

mm

mm

mm

 mm

5

5


1

Yes

Make: Model: Holden Cruze **Body Style:** Hatchback Year: 2016 Registration: KDD821 **Reg Expiry:** 01 Jul 2018 WoF Expiry: **Odometer:** 45,168 Kms **Good No:** 17744984 VIN: 6G1PD6EM9GL244901 **Next Service:** unknown Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Fine chips on screen.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

OK.

Interior Comments				
Seats	Good			
Carpets	Average			
Panels	Good			
Dashboard	Good			

Canaral	Commonts
Generai	Comments

Good manual hatch.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement:

Kms:

1 1/ ***	Conditioning / Heater		
$\exists \lceil \circ$	peration	~	
Ele	ctrical / Accessories		
Н	ead lights	~	
T	ail lights	~	
lr	dicators	~	
D	ashboard warning lights	~	
W	/ipers (front & rear)	~	
W	/indow winder FL	~	
, v	/indow winder FR	~	
W	/indow winder RL	~	
W	/indow winder RR	~	
R	ear view mirrors	~	
R	adio (basic test only)	~	
С	D (basic test only)	~	
N	umber of keys	2	
C	entral locking	~	
R	emote locking	~	
S	at. Nav. (basic test only)		·
R	eversing camera		·
	Date: 07 Dec 20	18	•

Inspected by:	Daryll Timms	

I have read and understood this condition guide.