

I have read and understood this condition guide.

Report ID: 17,746,026 Version: 4 Created: 23 Jul 2018

Signature:

Make:	Hyundai	Model:	lx35	Body Style:	SUV		Pass	Fail	N/A	
Year:	2,011	Registration:	HCF568	Reg Expiry:	28 Oct 2018	Engine				
WoF Expiry:	02 Jun 2018	Odometer:	170,841 Kms	Good No:	17746026	Oil level	~			
VIN:	KMHJT81BMBU24235	Next Service:	165,000kms	Service History	V: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	pration is made	for age and mileage	Parts have not	been dismontled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~			
						Performance	~			
Key:	S SC	-0	SDW S		s	Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent R = rust S D SC W D S W						Operation	v			
PT = paint defect						Noise	~			
C = crack					R SC	Clutch			~	
P = pin dent	HID				74 <u>11</u>	CV joints	~			
* = decals	SPSCW 91			- No	BID SW	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs SW SPW SDW SPW						Performance	~			
Bodylog		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)				
					Left front					
						Right front	7.		mm	
						Left rear	3.		mm	
Conditions During Body Inspection: Dry						Right rear	5.5		mm	
Conditions During Body Inspection: Dry						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater			1	
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
	Good					Tail lights	~			
Carpets	0000					Indicators	~			
Panels	Good					Dashboard warning lights	~			
	. Good					Wipers (front & rear)	~			
Dashboa	rd					Window winder FL	~			
	1					Window winder FR	~			
General C	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1		1	
Road Conditions During Test Drive: Dry						Central locking	· ·			
			U I J			Remote locking	~			
Engine Ti	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
Inspected by: Jason Young Date: 20 Apr 2018										

Name: