

Report ID: 17,746,312 Version: 1 Created: 08 May 2018

Make:	Subaru	Model:	Exiga	Body Style:	Wagon		Pass	Fail	N/A
Year:	2,008	Registration:		Reg Expiry:		Engine	1	I	ı
WoF Expiry:	10 Apr 2019	Odometer:	95,275 Kms	Good No:	17746312	Oil level	~		
VIN:	7AT0GF1RX18004796	Next Service:	105,240	Service Histor	' y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
						Operation	~		
R = rust PT = paint defect						Noise	~		
C = crack						Clutch	-		~
P = pin dent						CV joints	~		-
* = decals						Wheel bearings	~		
SC = stone chips							V		
W = significant scuffs						Brakes Performance	~		1
Redultance of the diagram Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed treat	-	ofture	
stone chips to F/screen Japanese satellite navigation system						Left front	· ·		
Japanese satellite havigation system								5	mm
						Right front		5	mm
[Left rear		5	mm
Conditions During Body Inspection: Dry						Right rear		5	mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
						Suspension	1		1
Clean and c	Iry					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
	Good					Electrical / Accessories		1	
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Runs and drives well						Window winder RR	~		1
						Rear view mirrors	~		1
						Radio (basic test only)	~		1
						CD (basic test only)	~		
						Number of keys	1	I	
Road Con	ditions During Too	Drive:				Central locking	~		
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	+		~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
	•	•							
Inspected by: Murray Craig Date: 08 May 2018									
I have read and understood this condition guide. Name:									