

Report ID: 17,746,429 Version: 1 Created: 17 May 2018

Make:	Volkswagen	Model:	Golf	Body Style:	Wagon		Pass	Fail	N/A
Year:	2,008	Registration:		Reg Expiry:		Engine			
WoF Expiry:	13 Apr 2019	Odometer:	72,583 Kms	Good No:	17746429	Oil level	~		
VIN:	WVWZZZ1KZ8M3396:	Next Service:	82500	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for any and milages	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	- HE			The		Operation	~		
R = rust PT = paint defe				$\prod$		Noise	~		
C = crack				$+ \mathbf{\nabla}$		Clutch	-		~
P = pin dent	HID				게비	CV joints	~		•
* = decals	616			The	<b>HIP</b>	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
		Note: son	ne defects & blemishes	mav not be disc	laved in the diagram	Hand Brake	~		
Body Insp	pection Comments			.,		Tyres (lowest observed tread	•	of tyre	es)
					Left front 3 mm				
						Right front			 
						Left rear		3	mm
Canalitian	- Dunin - Dadu Ina		_			Right rear			mm
Conditions During Body Inspection: Dry						Spare	3		
Under Carriage & Under Bonnet Inspection Comments						Suspension	Yes		
	<b>y</b>					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	V		
						Operation			
Interior Comments						Operation V Electrical / Accessories			
Good Good						Head lights			
Seats						-			
Carpets	Good					Tail lights Indicators	ン ン		
	Good						-		
Panels						Dashboard warning lights Wipers (front & rear)	<b>v</b>		
Dashboa	rd Good					Wipers (front & rear) Window winder FL	<b>v</b>		
						Window winder FL Window winder FR	<b>v</b>		
General (	Comments					Window winder FR Window winder RL	~		
						Window winder RL Window winder RR	<b>v</b>		
							~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Con	ditions During Test	: Drive:	Dry			Central locking	~		
Engine Tir	ming Mechanism:	Timing (	- hain			Remote locking	~		
-	of Cam Belt Replac			Kms:		Sat. Nav. (basic test only)			~
			lot Applicable	11113.		Reversing camera	~		
Inspected by: Brian Hill Date: 17 May 2018									
· · ·									

I have read and understood this condition guide.

Name: .....

Signature: .....