

Report ID: 17,746,570 Version: 1 Created: 27 Apr 2018

Make:	Subaru	Model:	Impreza	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,009	Registration:	impiczu	Reg Expiry:	natchoack	Engine			
WoF Expiry:		Odometer:	31,669 Kms	Good No:	17746570	Oil level	~		
VIN:	7AT0GF09X18014404		41,649kms	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		с I II	D	1 B 31 1	Noise	~		
	a guide only. Consid sting undertaken. The					Cooling System	•		
	ical inspection prior to					Coolant condition	~		
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	GIE			The		Operation	~		
R = rust				10	JHIH	Noise	~		
PT = paint def C = crack						Clutch	~		
P = pin dent	Ho					CV joints	~		
* = decals	- MIK			AL-		Wheel bearings	~		
SC = stone chi	ps U	20		A	&	Brakes	V		
W = significant scuffs						Performance			
		Noto: con	ne defects & blemishes		laved in the diagram		~		
Body Inst	pection Comments	Note: son	ne delects & blemisnes	inay not be disp	biayeu în the diagram	Hand Brake			
						Tyres (lowest observed tread depth of tyres)			
						Left front	5		mm
						Right front		1	mm
						Left rear		1	mm
Conditions During Body Inspection: Dry									mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	-	metmspectic	<u>on comments</u>			Suspension	L .		
Tidy and dr	у.					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
Interior Comments						Operation	~		
Good						Electrical / Accessories			1
Seats						Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
Ganaral	omments					Window winder FR	~		
General Comments Tidy, good driving hatch .						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanism:						Remote locking	~		
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)			~
Evidence	or Cam Beit Replac	ement: N	10	Kms:		Reversing camera			~
Inspecte	d by: Daryll Timms					Date: 27 Apr 20	18		
Inspecte							.0		

I have read and understood this condition guide.

Name:

Signature: