

Report ID: 17,748,002 Version: 1 26 Apr 2018 Created:

Make:	BMW	Model:	3 Series	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,000	Registration:	ZS1365	Reg Expiry:	05 Jun 2018	Engine			L
WoF Expiry:	07 Sep 2018	Odometer:	172,789 Kms	Good No:	17748002	Oil level	~		
VIN:	WBAAN56060NF0014	Next Service:	170,600	Service Histor	y: No	Smoke & fumes	~		
			·			Performance	r		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	r		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	V		
					·	Performance	V		
Key:	SW S	<u> </u>	SSCW SRW		/ W	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	s sc w			715	HIL SW	Operation	~		
PT = paint def	ect NP	F		$\left(\left \right\rangle \right)$		Noise	~		
C = crack					S W	Clutch			~
P = pin dent	GARGEN HID				74JUL	CV joints			~
* = decals	SRPSCWOR			To .	FID SRW	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = significan	S SC W S	w v	S P SC W S W		C P SC W	Performance	~		
Body Inc	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
Rubber on left rear door not fitting correctly. Rear left headlight is cracked. Stone chips in front windscreen.						Tyres (lowest observed tread depth of tyres)			2s)
Inner edge of rear left tyre quite worn.						Left front	t 6.6 m		
						Right front	6		mm
						Left rear	3		mm
Conditions During Body Inspection: Dry						Right rear		.0	mm
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Oil leak from	n both sides of engine.	oil leak from bet	ween engine and gear	box.		Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	ird					Window winder FL	~		
						Window winder FR	~		
General (<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	~		
	-					Remote locking	~		
-	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Anna-Lise Ferguson Date: 20 Apr 2018									

I have read and understood this condition guide.

Name:

Signature: