

Basic Vehicle Condition Guide

Report ID: 17,751,370

Version: 1


21 Jun 2019 Created:

Fail N/A

Make: Model: Holden Viva **Body Style:** Wagon Year: 2006 Registration: DKG595 Reg Expiry: 27 Jul 2019 **Odometer: WoF Expiry: Good No:** 13 Jun 2020 90,000 Kms 17751370 VIN: **Next Service:** KL3NF35BJ6K471353 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

RF door mirror casing scratched,

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	wear and tear,minor stains ,		
Carpets	wear and tear ,		
Panels	in rear scratched panels and stains ,		
Dashboard	middle console lid broken,glove box lid scratched		

General Comments

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

	1 033	i uii	14//(
Engine				
Oil level	~			
Smoke & fumes	V V			
Performance	~			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	\(\times \)			
Clutch	~			
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread	l depth	of tyre	s)	
Left front	-	7	mm	
Right front	-	7	mm	
Left rear	7		mm	
Right rear	;	7	mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	V V			
Shock absorbers	~			
Air Conditioning / Heater				
Operation 🗸				
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	\(\triangle \)			
Dashboard warning lights	~			
Wipers (front & rear)	~			
Window winder FL	~			
Window winder FR	\(\triangle \)			
Window winder RL	~			
Window winder RR	~			
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	1			
Central locking	~			
Remote locking	_			
Sat. Nav. (basic test only)			~	
Poversing camera				

Donovan Matara I have read and understood this condition guide.

Name:

Signature:

21 Jun 2019

Reversing camera