

Basic Vehicle Condition Guide

Report ID: 17,752,073

Version: 1


Created: 19 Jun 2019

Pass Fail N/A

Make: Model: Holden Astra **Body Style:** Hatchback Year: 2004 Registration: CDG185 Reg Expiry: 08 Jan 2020 WoF Expiry: **Odometer:** 10 May 2020 184,345 Kms **Good No:** 17752073 VIN: W0L0TGF4845133515 Next Service: 185000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments		
Seats	drivers seat ripped, wear and tear, minor stains ,	
Carpets	Average	
Panels	holes in hood lining ,	
Dashboard	Average	

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

Pass	Fail	N/A		
Engine				
~				
~				
~				
~				
~				
~				
~				
~				
~				
		~		
~				
~				
~				
'				
d depth	of tyre	es)		
3	3	mm		
3	3	mm		
7	7	mm		
6		mm		
	Yes			
~				
~				
~				
	~			
1				
~				
\(\triangle \)				
\(\times \)				
\(\times \)				
\(\times \)				
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \				
V V V V V V V				
V V V V V V V V				
v v				
\(\times \)				
\(\times \)				
\(\times \)				
\(\times \)				
V V V				
✓✓✓✓✓2				
✓✓✓✓✓2		· ·		
	3	V		

I have read and understood this condition guide.

Donovan Matara

Name:

Signature:

19 Jun 2019

Date: