

Report ID: 17,753,048 Version: 2 11 Jul 2019 Created:

Make:	Nissan	Model:	Navara	Body Style:	Utility		Pass	Fail	N/A
Year:	2010	Registration:	FFZ2	Reg Expiry:	27 Oct 2019	Engine	•		
WoF Expiry:	24 Jul 2020	Odometer:	182,165 Kms	Good No:	17753048	Oil level	~		
VIN:	MNTNCUD40A000330	Next Service:	192000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	r an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust						Operation	~		
PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent	HIP				7414	CV joints	~		
* = decals SC 919						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
Podylog	action Commonts	Note: son	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
Body Inspection Comments Steering wheel were						Tyres (lowest observed tread depth of tyres)			
Steering wheel worn,						Left front 7.0 m			mm
						Right front	7	.0	mm
						Left rear		.0	mm
Conditions During Body Inspection: Dry						Right rear		.0	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Oil seepage	lower engine area,					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	L					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL			~
/						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Con	ditions During Test	Central locking	~						
			Dry			Remote locking	~		
Engine Ti	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Chris Buckley Date: 27 Jun 2019									

I have read and understood this condition guide.

Name:

Signature: