

Basic Vehicle Condition Guide

Report ID: 17,754,616


Version: 1

Created: 02 Aug 2019

Make: Model: Holden Rodeo 4X2 **Body Style:** Utility Year: 2007 Registration: EAJ715 Reg Expiry: 01 Jul 2019 WoF Expiry: **Odometer: Good No:** 02 Aug 2020 261,483 Kms 17754616 VIN: MPATFR85H7H56643; Next Service: 171500 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

LR tail light cracked,

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Average		

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Donovan Matara Inspected by:

Name:

Cleate	u. 0.	z Aug z	2017
	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	V		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch	\(\times \)		
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front		7	mm
Right front	7		mm
Left rear	4		mm
Right rear	4		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater	!	ļ	!
Operation	~		
Electrical / Accessories	l		1
Head lights	~		
Tail lights	~		
Indicators			
Dashboard warning lights	V		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	·		
Remote locking	<u></u>		
Sat. Nav. (basic test only)			~
Reversing camera			\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
reising culliciu			

02 Aug 2019

Signature:

Date: