

Report ID: 17,754,895 Version: 2 16 Jun 2020 Created:

Signature: .....

Make:	Mazda	Model:	Bt-50	Body Style:	Utility		Pass	Fail	N/A
Year:	2012	<b>Registration:</b>	GPF996	<b>Reg Expiry:</b>	08 Sep 2020	Engine			
WoF Expiry:	15 Jul 2020	Odometer:	248,738 Kms	Good No:	17754895	Oil level	~		
VIN:	MM0UP0YF10012284	Next Service:	236000	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
			S D SC			Performance	~		
Key:		-0	SDSC			Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust						Operation	~		
PT = paint defe	ect NP	r I		$\left( \left  \left( \right) \right\rangle \right)$		Noise	~		
C = crack					SC	Clutch	~		
P = pin dent	HID				7414	CV joints	~		
*=decals						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC S SC						Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Minor stone chips in windscreen ,						Tyres (lowest observed tread depth of tyres)			es)
						Left front	-	7	mm
						Right front	<del>,</del>	7	mm
						Left rear	e	5	mm
Conditions During Body Inspection: Wet						Right rear	6 mm		mm
terranie zamię zedy mopecnem wiet						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		
						Operation		~	
Interior Comments						Electrical / Accessories	1		1
Seats	cigarette h	noles,wear and te	ear,worn ,			Head lights	~		
	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	scratches t	top of dashboarc	Ι,			Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	~		
	-					Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Donovan Matara Date: 16 Jun 2020									

I have read and understood this condition guide.

Name: .....