

Basic Vehicle Condition Guide

Report ID: 17,755,540


Version: 2

Created: 18 Sep 2018

Make: Model: Crown **Body Style:** Sedan Toyota Year: 2006 Registration: Reg Expiry: **WoF Expiry: Odometer: Good No:** 98,720 Kms 15 Aug 2019 17755540 VIN: 7AT0H60BX18021106 **Next Service:** 108700 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

Wet

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:** No

Kms:

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	V V		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	•	•	•
Operation	~		
Noise	~		
Clutch			~
CV joints			~
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	4.5		mm
Right front	4.5		mm
Left rear	4.0		mm
Right rear	4.0		mm
Spare		Yes	
Suspension	•		
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	V V V V V V		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			.,

Reversing camera

Signature:

16 Aug 2018 Inspected by: Xinghui Lin