

Basic Vehicle Condition Guide

Report ID: 17,755,627


Version:

Created: 20 Aug 2018

Make: Model: Subaru **Body Style:** Sedan Impreza Year: 2,011 Registration: Reg Expiry: **WoF Expiry: Odometer: Good No:** 16 Aug 2019 92,877 Kms 17755627 VIN: 7AT0GF0BX18003299 **Next Service:** 102,000kms **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments					
Seats	Good				
Carpets	Good				
Panels	Good				
Dashboard	Good				

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

Name:

Ca Thach 16 Aug 2018

٦		_					
		Pass	Fail	N/A			
	Engine						
	Oil level	-					
	Smoke & fumes	\(\times \)					
	Performance	~					
	Cooling System						
_	Coolant condition	V V					
	Performance	~					
	Radiator / Hoses (visual)	~					
	Transmission						
	Operation	~					
	Noise	~					
	Clutch			~			
	CV joints	~					
	Wheel bearings	~					
	Brakes						
	Performance	~					
	Hand Brake	~					
	Tyres (lowest observed tread depth of tyres)						
	Left front	5	.0	mm			
	Right front	5.0		mm			
	Left rear	6	.0	mm			
	Right rear	6.0		mm			
_ _	Spare Yes						
	Suspension						
	Suspension performance	~					
	Steering performance	~					
	Shock absorbers	~					
	Air Conditioning / Heater						
_ 	Operation	~					
	Electrical / Accessories						
	Head lights	~					
	Tail lights	~					
	Indicators	~					
	Dashboard warning lights	~					
	Wipers (front & rear)	~					
	Window winder FL	V V V V V V V V					
	Window winder FR	~					
	Window winder RL	~					
	Window winder RR	~					
	Rear view mirrors	~					
	Radio (basic test only)	~					
	CD (basic test only)	~					
	Number of keys	2	<u> </u>	1			
٦	Central locking	~					
<u>_</u>	Remote locking	~					
]	Sat. Nav. (basic test only)			V			
	Reversing camera			~			
		<u> </u>	<u> </u>				
	Dato: 16 Aug 20	1 Q					

Signature: