

## **Basic Vehicle Condition Guide**

Report ID: 17,755,643

Version: 2


Created: 20 Aug 2018

Make: Model: Hiace **Body Style:** Toyota Van Year: 2,013 Registration: Reg Expiry:

**WoF Expiry: Odometer: Good No:** 16 Aug 2019 107,324 Kms 17755643 VIN: 7AT0H60FX18111833 **Next Service: Service History:** 117322

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

**Conditions During Body Inspection:** Wet

**Under Carriage & Under Bonnet Inspection Comments** 

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

**General Comments** 

Inspected by:

Road Conditions During Test Drive: Wet

**Engine Timing Mechanism:** Cambelt

Xinghui Lin

**Evidence of Cam Belt Replacement:** Kms: Yes 100,797

Date:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	V		
Noise	~		
Cooling System		•	
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission		•	
Operation	~		
Noise	~		
Clutch			~
CV joints			~
Wheel bearings	~		
Brakes		•	
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	4	.0	mm
Right front	4	.0	mm
Left rear	5	.0	mm
Right rear	5.0		mm
Spare		Yes	
Suspension			
Suspension performance	>		
Steering performance	V		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	>		
Electrical / Accessories			
Head lights	~		
Tail lights	>		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Window winder FL	~		
Window winder FR	~		
Window winder RL			~
Window winder RR			~
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	3		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			<b>'</b>

I have read and understood this condition guide.

Name: .....

Signature: .....

16 Aug 2018