

Basic Vehicle Condition Guide

Report ID: 17,755,823


Version: 1

Created: 12 Sep 2018

Make: Model: IS350 **Body Style:** Sedan Lexus Year: 2,007 Registration: Reg Expiry: **WoF Expiry: Odometer: Good No:** 11 Sep 2019 96,165 Kms 17755823 VIN: **Next Service:** 7AT0B00HX18018314 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Under Carriage & Under Bonnet Inspection Comments

Conditions During Body Inspection:

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

Wet

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Xinghui Lin Date: 12 Sep 2018

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints			~
Wheel bearings	~		
Brakes	•	•	
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front		1	mm
Right front	4		mm
Left rear	4	1	mm
Right rear	4		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater	ı		ı
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	V V V V V		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2	I	1
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	~		
L			

Signature: