

Report ID: 17,756,004 Version: 1 Created: 19 Sep 2018

Make:	Mitsubishi	Model:	Outlander	Body Style:	SUV		Pass	Fail	N/A
Year:	2014	Registration:		Reg Expiry:		Engine			
WoF Expiry:	18 Sep 2019	Odometer:	99,123 Kms	Good No:	17756004	Oil level	~		
VIN:	7AT0CJ3MX18012097	Next Service:		Service Histor	' y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	avation is made	for one and miles as	Danta hava nai	hoop disponsion of	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional	charge.	Coolant condition	~		
						Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	- HE			TIN		Operation	~		
R = rust PT = paint defe				$\left(\left \right\rangle \right)$		Noise	~		
C = crack				+		Clutch	-		~
P = pin dent						CV joints	~		•
* = decals	616			- NL	ELLE	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
		Note: som	ne defects & blemishes	may not be disi	plaved in the diagram	Hand Brake	~		
Body Insp	pection Comments					Tyres (lowest observed tread		of tyre	s)
					Left front				
						Right front	5		mm
						Left rear	5		mm
						Right rear	5		
Conditions During Body Inspection: Wet						Spare	5 mm		
Under Carriage & Under Bonnet Inspection Comments						Suspension	N/A		
						Suspension performance	~		
						Steering performance	v v		
						Shock absorbers			
							~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Good						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Good					Tail lights Indicators	~		
	Good						~		
Panels						Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
General	<u>Comments</u>					Window winder FR	~		
	<u>comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
Engine Ti	ming Mechanism:	Time !:= = /				Remote locking	~		
•	•	Timing (Kmc		Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Xinghui Lin Date: 19 Sep 2018									

I have read and understood this condition guide.

Name:

Signature: