



Turners Certified Imports 50 Point Check

Report ID: 17,756,983
Version: 1
Created: 14 Dec 2018

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make: Toyota Body Style: People Mover
Model: Regius Odometer: 82,163 Kms
Year: 2014 VIN: 7AT0H63TX18209306

Under Carriage & Under Bonnet Inspection Comments

General Comments

Seats: Good

Carpets: Good

Panels: Good

Dashboard: Good

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable

Replaced At (odometer reading):

Road Conditions During Test Drive: Dry

Electrical

Battery	☒
Head lights	☒
Tail lights	☒
Indicators	☒
Dashboard warning lights	☒
Wipers (front & rear)	☒
Window winder FL	☒
Window winder FR	☒
Window winder RL	☒
Window winder RR	☒
Rear view mirrors	☒
Radio (basic test only)	☒
CD (basic test only)	☒
Reversing camera	☐

Transmission & Drive

Operation	☒
Noise	☒
Clutch	☐
CV joints	☐
Wheel bearings	☒
Wheel balance	☒

Brakes

Performance	☒
Hand Brake	☒

Keys & Locking

Central locking	☒
Remote locking	☒
Number of keys	1

Engine

Oil level	☒
Smoke & fumes	☒
Performance	☒
Noise	☒

Cooling System

Coolant condition	☒
Performance	☒
Radiator / Hoses (visual)	☒

Suspension

Suspension performance	☒
Steering performance	☒
Shock absorbers	☒

Tyres (lowest observed tread depth)

Left front	5.5 mm
Right front	5.5 mm
Left rear	5.0 mm
Right rear	8.0 mm
Spare	Yes
Tools	☒

Interior

AC Operation	☒
Heater fan	☐
Seatbelts	☒
Horn	☒

Turners Certified Key

✓ = Pass X = Fail
• = Not applicable for this vehicle

Inspected by: Ca Thach

Date: 11 Dec 2018

I have read and understood this condition guide.

Name:

Signature: