

Report ID: 17,758,035 Version: 1 23 Dec 2018 Created:

Make:	Hyundai	Model:	Sonata	Body Style:	Sedan		Pass	Fail	N/A
Year:	2008	Registration:	ELU1	Reg Expiry:	01 Jul 2019	Engine			
WoF Expiry:		Odometer:	129,546 Kms	Good No:	17758035	Oil level	~		
VIN:	KMHEU41FR7A35213			Service Histor		Smoke & fumes	~		
					, 110	Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		
Key:		-0	P P			Radiator / Hoses (visual)	~		
S = scratch	ST	0	$\overline{\frown}$	10/2	*	Transmission	V		
D = dent	s sc				EID S		~		<u> </u>
R = rust				TIO		Operation Noise	~		
PT = paint defe	ect			+	SC	Clutch	~		\vdash
C = crack P = pin dent	LHC								~
* = decals	sc pp					CV joints	~		
SC = stone chips						Wheel bearings			
W = significant scuffs S W S						Brakes			.
						Performance		~	
<u>Body Ins</u> p	pection Comments	Note: som	ne defects & blemishe	es may not be disp	layed in the diagram	Hand Brake	~		
Aftermarket wheels fitted						Tyres (lowest observed tread depth of tyres)			
						Left front	3.	.5	mm
						Right front	3.	.5	mm
						Left rear	3.	3.5 mr	
Conditions During Body Inspection: Wet						Right rear	3.	3.5 mr	
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
Under Ca	irriage & Under Bor	net Inspectio	on Comments			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	_		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	Average					Wipers (front & rear)	~		
	ird					Window winder FL	~		
						Window winder FR	~		1
General Comments						Window winder RL	~		
Passenger side sun visor insecure Drive belt very noisy when cold start						Window winder RR	~		
Spongy bra						Rear view mirrors	~		1
						Radio (basic test only)	~		1
						CD (basic test only)	~		1
						Number of keys	2		1
Road Con	ditions During Tes	t Drive:	Wet			Central locking	~		1
						Remote locking	~		1
Engine Ti	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
·						Ĺ	1		
Inspecte	d by: Xinghui Lin					Date: 23 Dec 20	18		

I have read and understood this condition guide.

Name:

Signature: