



Turners Certified Imports 50 Point Check

Report ID: 17,758,280

Version: 1

Created: 09 Jan 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make: Toyota

Body Style:

Model: Noah

Odometer: 69,373 Kms

Year: 2005

VIN: 7AT0H64NX18472339

Under Carriage & Under Bonnet Inspection CommentsGeneral Comments

Seats: Good

Carpets: Good

Panels: Good

Dashboard: Good

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable

Replaced At (odometer reading):

Road Conditions During Test Drive: Dry

Electrical

| | |
|--------------------------|-------------------------------------|
| Battery | <input checked="" type="checkbox"/> |
| Head lights | <input checked="" type="checkbox"/> |
| Tail lights | <input checked="" type="checkbox"/> |
| Indicators | <input checked="" type="checkbox"/> |
| Dashboard warning lights | <input checked="" type="checkbox"/> |
| Wipers (front & rear) | <input checked="" type="checkbox"/> |
| Window winder FL | <input checked="" type="checkbox"/> |
| Window winder FR | <input checked="" type="checkbox"/> |
| Window winder RL | <input checked="" type="checkbox"/> |
| Window winder RR | <input checked="" type="checkbox"/> |
| Rear view mirrors | <input checked="" type="checkbox"/> |
| Radio (basic test only) | <input checked="" type="checkbox"/> |
| CD (basic test only) | <input checked="" type="checkbox"/> |
| Reversing camera | <input checked="" type="checkbox"/> |

Transmission & Drive

| | |
|----------------|-------------------------------------|
| Operation | <input checked="" type="checkbox"/> |
| Noise | <input checked="" type="checkbox"/> |
| Clutch | <input type="checkbox"/> |
| CV joints | <input checked="" type="checkbox"/> |
| Wheel bearings | <input checked="" type="checkbox"/> |
| Wheel balance | <input checked="" type="checkbox"/> |

Brakes

| | |
|-------------|-------------------------------------|
| Performance | <input checked="" type="checkbox"/> |
| Hand Brake | <input checked="" type="checkbox"/> |

Keys & Locking

| | |
|-----------------|-------------------------------------|
| Central locking | <input checked="" type="checkbox"/> |
| Remote locking | <input checked="" type="checkbox"/> |
| Number of keys | 1 |

Engine

| | |
|---------------|-------------------------------------|
| Oil level | <input checked="" type="checkbox"/> |
| Smoke & fumes | <input checked="" type="checkbox"/> |
| Performance | <input checked="" type="checkbox"/> |
| Noise | <input checked="" type="checkbox"/> |

Cooling System

| | |
|---------------------------|-------------------------------------|
| Coolant condition | <input checked="" type="checkbox"/> |
| Performance | <input checked="" type="checkbox"/> |
| Radiator / Hoses (visual) | <input checked="" type="checkbox"/> |

Suspension

| | |
|------------------------|-------------------------------------|
| Suspension performance | <input checked="" type="checkbox"/> |
| Steering performance | <input checked="" type="checkbox"/> |
| Shock absorbers | <input checked="" type="checkbox"/> |

Tyres (lowest observed tread depth)

| | |
|-------------|-------------------------------------|
| Left front | 6.0 mm |
| Right front | 6.0 mm |
| Left rear | 6.0 mm |
| Right rear | 6.0 mm |
| Spare | Yes |
| Tools | <input checked="" type="checkbox"/> |

Interior

| | |
|--------------|-------------------------------------|
| AC Operation | <input checked="" type="checkbox"/> |
| Heater fan | <input checked="" type="checkbox"/> |
| Seatbelts | <input checked="" type="checkbox"/> |
| Horn | <input checked="" type="checkbox"/> |

Turners Certified Key

✓ = Pass ✗ = Fail
• = Not applicable for this vehicle

Inspected by: Ca Thach

Date: 04 Jan 2019

I have read and understood this condition guide.

Name:

Signature: