



Turners Certified Imports 50 Point Check

Report ID: 17,759,178

Version: 1

Created: 31 Jan 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make: Subaru Body Style: Wagon
Model: Legacy Odometer: 128,393 Kms
Year: 2010 VIN: 7AT0GF16X19038514

Under Carriage & Under Bonnet Inspection CommentsGeneral Comments

Seats: Good

Carpets: Good

Panels: Good

Dashboard: Good

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Replaced At (odometer reading):

Road Conditions During Test Drive: Dry

Electrical

Battery	<input checked="" type="checkbox"/>
Head lights	<input checked="" type="checkbox"/>
Tail lights	<input checked="" type="checkbox"/>
Indicators	<input checked="" type="checkbox"/>
Dashboard warning lights	<input checked="" type="checkbox"/>
Wipers (front & rear)	<input checked="" type="checkbox"/>
Window winder FL	<input checked="" type="checkbox"/>
Window winder FR	<input checked="" type="checkbox"/>
Window winder RL	<input checked="" type="checkbox"/>
Window winder RR	<input checked="" type="checkbox"/>
Rear view mirrors	<input checked="" type="checkbox"/>
Radio (basic test only)	<input checked="" type="checkbox"/>
CD (basic test only)	<input checked="" type="checkbox"/>
Reversing camera	<input type="checkbox"/>

Transmission & Drive

Operation	<input checked="" type="checkbox"/>
Noise	<input checked="" type="checkbox"/>
Clutch	<input type="checkbox"/>
CV joints	<input checked="" type="checkbox"/>
Wheel bearings	<input checked="" type="checkbox"/>
Wheel balance	<input checked="" type="checkbox"/>

Brakes

Performance	<input checked="" type="checkbox"/>
Hand Brake	<input checked="" type="checkbox"/>

Keys & Locking

Central locking	<input checked="" type="checkbox"/>
Remote locking	<input checked="" type="checkbox"/>
Number of keys	1

Engine

Oil level	<input checked="" type="checkbox"/>
Smoke & fumes	<input checked="" type="checkbox"/>
Performance	<input checked="" type="checkbox"/>
Noise	<input checked="" type="checkbox"/>

Cooling System

Coolant condition	<input checked="" type="checkbox"/>
Performance	<input checked="" type="checkbox"/>
Radiator / Hoses (visual)	<input checked="" type="checkbox"/>

Suspension

Suspension performance	<input checked="" type="checkbox"/>
Steering performance	<input checked="" type="checkbox"/>
Shock absorbers	<input checked="" type="checkbox"/>

Tyres (lowest observed tread depth)

Left front	7.0 mm
Right front	7.0 mm
Left rear	7.0 mm
Right rear	7.0 mm
Spare	Yes
Tools	<input checked="" type="checkbox"/>

Interior

AC Operation	<input checked="" type="checkbox"/>
Heater fan	<input checked="" type="checkbox"/>
Seatbelts	<input checked="" type="checkbox"/>
Horn	<input checked="" type="checkbox"/>

Turners Certified Key

✓ = Pass ✗ = Fail
• = Not applicable for this vehicle

Inspected by: Mathew Varghese

Date: 20 Jan 2019

I have read and understood this condition guide.

Name:

Signature: