

Turners Certified Imports 50 Point Check

Report ID: 17,759,355 Version: 1 22 Jan 2019 Created:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Nissan	Body Style:	SUV
Model:	X-Trail	Odometer:	123,841 Kms
Year:	2007	VIN:	7AT0DH6LX19002737

Under Carriage & Under Bonnet Inspection Comments

	Seats:	Good	
	Carpets:	Good	
]	Panels:	Good	
	Dashboard:	Good	
	Engine Timing Mechanism:		Timing Chain
	Evidence of	Cam Belt Replacement:	Not Applicable

General Comments

Replaced At (odometer reading): Dry Road Conditions During Test Drive:

				houd conditions builting rest brive.				
Electrical		Transmission & Drive		Engine		Tyres (lowest observed tread depth)		
Battery		Operation		Oil level		Left front	4.0	mm
Head lights		Noise		Smoke & fumes		Right front	4.0	mm
ail lights		Clutch	•	Performance		Left rear	5.0	mm
ndicators		CV joints		Noise		Right rear	5.0	mm
ashboard warning light	ts	Wheel bearings		Cooling System		Spare	Yes	
/ipers (front & rear)		Wheel balance		Coolant condition		Tools		,
/indow winder FL		Brakes		Performance		Interior		
/indow winder FR		Performance		Radiator / Hoses (visual)		AC Operation		/
indow winder RL		Hand Brake				Heater fan		
indow winder RR				Suspension		Seatbelts		
ear view mirrors		Keys & Locking		Suspension performance		Horn		
adio (basic test only)		Central locking		Steering performance				
D (basic test only)		Remote locking		Shock absorbers		 Turners Certified ✓ = Pass ● = Not applica 	🗙 = Fail	hicle
Reversing camera	•	Number of keys	1	Inspected by: Mathew Var	ghese		21 Jan 2019	_

Name:

Signature: