

Basic Vehicle Condition Guide

Report ID: 17,760,443


Version: 1

07 Dec 2018 Created:

Make: Model: Ssangyong Korando **Body Style:** SUV Year: 2005 Registration: **DBN253** Reg Expiry: 07 Feb 2019 **Odometer:** Good No: WoF Expiry: 14 Dec 2019 53,918 Kms 17760443 VIN: KPTM2C19S4P238790 Next Service: 64,000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

minor Oil leaks. Underbody surface rust Rear brakes low

| <u>Interior Comments</u> | | | |
|--------------------------|---------|--|--|
| Seats | Average | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Average | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Scott Willoughby 07 Dec 2018 Inspected by: Date:

Name:

| | Pass | Fail | N/A | | |
|------------------------------|--|---------|-----|--|--|
| Engine | | 1 | | | |
| Oil level | ~ | | | | |
| Smoke & fumes | ~ | | | | |
| Performance | \(\times \) | | | | |
| Noise | ~ | | | | |
| Cooling System | 1 | 1 | | | |
| Coolant condition | ~ | | | | |
| Performance | ~ | | | | |
| Radiator / Hoses (visual) | ~ | | | | |
| Transmission | | | | | |
| Operation | ~ | | | | |
| Noise | ~ | | | | |
| Clutch | | | ~ | | |
| CV joints | ~ | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | | | | | |
| Performance | ~ | | | | |
| Hand Brake | ~ | | | | |
| Tyres (lowest observed tread | d depth | of tyre | es) | | |
| Left front | 4.0 | | mm | | |
| Right front | 2 | | mm | | |
| Left rear | 4.0 | | mm | | |
| Right rear | 4.0 mm | | mm | | |
| Spare | Yes | | | | |
| Suspension | | | | | |
| Suspension performance | ~ | | | | |
| Steering performance | ~ | | | | |
| Shock absorbers | ~ | | | | |
| Air Conditioning / Heater | | | | | |
| Operation 🗸 | | | | | |
| Electrical / Accessories | | | | | |
| Head lights | ~ | | | | |
| Tail lights | ~ | | | | |
| Indicators | \(\times \) \(\t | | | | |
| Dashboard warning lights | ~ | | | | |
| Wipers (front & rear) | ~ | | | | |
| Window winder FL | ~ | | | | |
| Window winder FR | ~ | | | | |
| Window winder RL | | | ~ | | |
| Window winder RR | | | ~ | | |
| Rear view mirrors | ~ | | | | |
| Radio (basic test only) | ~ | | | | |
| CD (basic test only) | ~ | | | | |
| Number of keys | 1 | | • | | |
| Central locking | ~ | | | | |
| Remote locking | ~ | | | | |
| Sat. Nav. (basic test only) | | | ~ | | |
| Reversing camera | | | ~ | | |
| | | | | | |

Signature: