

Report ID: 17,760,979 Version: 2 20 Mar 2019 Created:

Make:	Hyundai	Model:	Sonata	Body Style:	Sedan		Pass	Fail	N/A
Year:	2015	Registration:	HYZ187	Reg Expiry:	12 Feb 2019	Engine			
WoF Expiry:	16 Feb 2019	Odometer:	72,158 Kms	Good No:	17760979	Oil level	~		
VIN:	KMHE241FMFA08134	Next Service:	82000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for any and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	r an additional o	charge.	Coolant condition	~		
	S		S S		Р	Performance	~		
Key:	B	$-\infty$	S S			Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	s dia			215	HIVS	Operation	~		
PT = paint defe		r I		$\left[\left(\right) \right]$		Noise	~		
C = crack						Clutch			~
P = pin dent	s dP				74116	CV joints	~		
* = decals				10	ELC'S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv – signincan	S		S S		S D	Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
					Left front	nt 3 mi			
						Right front	3	;	mm
						Left rear	7	,	mm
Conditions During Body Inspection: Wet						Right rear	6 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
Shock							~		
						Air Conditioning / Heater	Conditioning / Heater		
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Compete	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Darkle	Good					Wipers (front & rear)	~		
Dashboa	iru					Window winder FL	~		
	_					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry							~		
Remote locking							~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test on									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Bobby Zhong Date: 20 Mar 2019									
Inspected by. Dobby Zhong Date: 20 Mai 2019									

I have read and understood this condition guide.

Name:

Signature: