

Report ID: 17,761,400 Version: 4 12 Feb 2019 Created:

Make:	Mazda	Model:	CX-9	Body Style:	SUV		Pass	Fail	N/A
Year:	2015	Registration:	JMW945	Reg Expiry:	07 Mar 2019	Engine			
WoF Expiry:	07 Feb 2020	Odometer:	132,194 Kms	Good No:	17761400	Oil level	~		
VIN:	JM0TB10A5G0443517	Next Service:	133500	Service Histor	y: Yes	Smoke & fumes	~		
Note: This						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
	ical inspection phot to	purchase and t	his can be analiged to		Linarge.	Coolant condition	~		
Kan	SC		S D S		S	Performance	~		
Key: S = scratch		$\overline{(0)}$		5(O)-		Radiator / Hoses (visual)	~		
D = dent						Transmission			
R = rust	s Alb	\square				Operation	~		
PT = paint defe	ect NM					Noise	~		
C = crack						Clutch			~
P = pin dent * = decals	s dk				~HHs	CV joints	~		
SC = stone chi		10		70		Wheel bearings	~		
W = significant scuffs						Brakes			
	S	\sim	S			Performance	~		
Body Insp	pection Comments	Note: son	ne defects & blemishes	s may not be disp	played in the diagram	Hand Brake	~		
Damage to front bumper						Tyres (lowest observed tread depth of tyres)			
						Left front	2.	0	mm
						Right front	2.	0	mm
						Left rear	8.	0	mm
Conditions During Body Inspection: Dry						Right rear 8.0 mm			mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
Under Ca	rrlage & Under Bor	inet inspectio	on Comments			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1 1		1
Interior Comments						Operation	~		
Good						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	Good Good					Wipers (front & rear)	~		
						Window winder FL	~		
General	<u>Comments</u>					Window winder FR	~		
						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Tir	ming Mechanism	Timing	Chain			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
		ement. P	lot Applicable	11115.		Reversing camera	~		
Inspected by: Jeff Luke Date: 09 Jan 2019									

I have read and understood this condition guide.

Name:

Signature: