

Report ID: 17,762,084 Version: 1 06 May 2019 Created:

Signature:

| Make: | Ford | Model: | Focus | Body Style: | Hatchback | | Pass | Fail | N/A |
|--|---|----------------------|------------------------|--|----------------------|--|--------|----------|-----|
| Year: | 2016 | Registration: | JUM923 | Reg Expiry: | 19 May 2019 | Engine | | | |
| WoF Expiry: | 30 Apr 2020 | Odometer: | 34,998 Kms | Good No: | 17762084 | Oil level | ~ | | |
| VIN: | MPB3XXMXC3GA4044 | Next Service: | 52000 | Service Histor | y: Yes | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty a quide only. Conside | eration is made | for age and mileage | . Parts have not | been dismantled or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechar | lical inspection prior to | purchase and ti | his can be arranged fo | or an additional o | narge. | Coolant condition | ~ | | |
| | | | C | | | Performance | ~ | | |
| Key: | | -0 | | | | Radiator / Hoses (visual) | ~ | | |
| S = scratch D = dent | TE | | | | Tan | Transmission | | | I |
| B = rust | s dis | | | 710 | HIVS | Operation | ~ | | |
| PT = paint def | | r I | | $\left(\left \left(\right) \right\rangle \right)$ | | Noise | ~ | | |
| C = crack | | | | | | Clutch | | | ~ |
| P = pin dent | HIG | | | | 74116 | CV joints | ~ | | |
| * = decals | s alk | | | | | Wheel bearings | V | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significant scuffs | | | | | | Performance | ~ | | |
| Body Inc | pection Commonts | Note: son | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | ~ | | |
| Body Inspection Comments | | | | | | Tyres (lowest observed tread depth of tyres) | | | 2S) |
| | | | | | | Left front | | .0 | mm |
| | | | | | | Right front | 4 | .0 | mm |
| | | | | | | Left rear | | .0 | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 5.0 mr | | mm |
| | | | | | | Spare Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | V | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | 1 | | |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| | Good | | | | | Tail lights | ~ | <u> </u> | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| | , Good | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | ard Good | | | | | Window winder FL | ~ | | |
| | 1 | | | | | Window winder FR | ~ | | |
| General (| <u>Comments</u> | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 2 | L | |
| Road Con | ditions During Tes | t Drive: | Dry | | | Central locking | ~ | | |
| | | . 2000 | | | | Remote locking | ~ | | |
| Engine Ti | ming Mechanism: | Timing | Chain | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | ~ | | |
| | | | | | | | | | |
| Inspecte | d by: Jeff Luke | | | | | Date: 05 Feb 20 | 19 | | |

I have read and understood this condition guide.

Name: