

Basic Vehicle Condition Guide

Report ID: 17,762,130


Version: 1

Created: 14 Feb 2019

Make: Model: Toyota Hilux **Body Style:** Utility Year: 2011 Registration: FZF693 Reg Expiry: 29 Sep 2019 WoF Expiry: **Odometer:** 03 Oct 2019 211,525 Kms **Good No:** 17762130 VIN: MR0FZ22G601048510 Next Service: 220,000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Underbody surface rust

| Interior Comments | | | |
|-------------------|---------|--|--|
| Seats | Average | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Average | | |

| | _ |
|---------|----------|
| General | Comments |

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes

Scott Willoughby

Kms: 150,000

| | D | F - 11 | NI/A |
|------------------------------|--|---------|----------|
| | Pass | Fail | N/A |
| Engine | | | |
| Oil level | • | | |
| Smoke & fumes | ν ν | | |
| Performance | • | | |
| Noise | • | | |
| Cooling System | | | |
| Coolant condition | - | | |
| Performance | <i>V</i> | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | 6 | .0 | mm |
| Right front | 6.0 | | mm |
| Left rear | 8 | .0 | mm |
| Right rear | 8 | .0 | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | V | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | ı | | 1 |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | \(\times \) \(\t | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | V V V | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 1 | | 1 |
| Central locking | · | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | 1 |
| Reversing camera | | | |
| neversing carriera | | | |

I have read and understood this condition guide.

Name:

Signature:

07 Feb 2019