

 Report ID:
 17,762,195

 Version:
 1

 Created:
 13 Feb 2019

Make:	Ford	Model:	Mondeo	Body Style:	Sedan		Pass	Fail	N/A
Year:	2008	Registration:	EKQ396	Reg Expiry:	10 Jul 2019	Engine			
WoF Expiry:	04 May 2019	Odometer:	182,653 Kms	Good No:	17762195	Oil level	~		
VIN:	WF0DXXGBBD7M556	Next Service:	176000	Service Histor	r y: Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:	sc	-0	SC D	-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	ssc 6/6			The	EL SC	Operation	~		
R = rust				10	JHIH	Noise	~		
PT = paint defects C = crack				+		Clutch			~
P = pin dent	Ho	KI				CV joints	~		
* = decals	SP PIC			AL-		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC SC SC									
		Nata				Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~	<u> </u>	Ļ
						Tyres (lowest observed tread depth of tyres)			
						Left front		.0	mm
						Right front	3	.0	mm
						Left rear	4	.0	mm
Conditions During Body Inspection: Dry						Right rear			
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension		1	1
Rear crank	seal leaking					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	-		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Poor					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1	I	1
Road Conditions During Test Driver Driver						Central locking	· ·		
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	-		V
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			v v
	-1	·							•
Inspected by: Dion Mair Date: 12 Feb 2019									

I have read and understood this condition guide.

Name:

Signature: