

## **Basic Vehicle Condition Guide**

Report ID: 17,765,197


Version: 1

Created: 07 May 2019

Make: Model: **Body Style:** Utility Isuzu D-MAX Year: 2013 Registration: G02W0 Reg Expiry: 26 Aug 2019 **WoF Expiry: Odometer: Good No:** 18 Aug 2019 157,633 Kms 17765197 VIN: MPATFS85JDT005587 **Next Service:** Service History:

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Engine rattle

Interior Comments				
Seats	Average			
Carpets	Average			
Panels	Average			
Dashboard	Average			

	_
General	Comments

Inspected by:

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism: Timing Chain** 

**Evidence of Cam Belt Replacement:** Not Applicable Kms:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance		~	
Noise		~	
Cooling System			
Coolant condition	<b>'</b>		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission		•	
Operation	~		
Noise	V		
Clutch	~		
CV joints			~
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed treac	depth	of tyre	es)
Left front	5	.0	mm
Right front	8.0		mm
Left rear	8.0		mm
Right rear	8	.0	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	<b>V</b>		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			1
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	\( \times \)		
Wipers (front & rear)			
Window winder FL	~		
Window winder FR	\( \triangle \)		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	3		I
Central locking	<i>'</i>		
Remote locking	<i>V</i>		
Sat. Nav. (basic test only)			· /
Reversing camera			\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
eversing cumera			

I have read and understood this condition guide.

Jeff Luke

Name:			

Signature: .....

02 May 2019

Date: