

Turners Certified Imports 50 Point Check

Report ID: 17,765,676

Version:

Created: 31 Jan 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Toyota	Body Style:	Wagon					
Model:	Markx	Odometer:	105,648 Kms					
Year:	2007	VIN:	7AT0H64TX19001232					
Under Carriage & Under Bonnet Inspection Comments								
Onder	camage a onder bo	meemspee	tuon comments					

Dashboard:	dod
Dashboard:	Good
Panels:	Good
Carpets:	Good
Seats:	Good

General Comments		

Engine Timing Mechanism:

Evidence of Cam Belt Replacement:

Not Applicable

Replaced At (odometer reading):

Road Conditions During Test Drive:

Dry







