

Report ID: 17,765,695


Version: 1

Created: 30 Jan 2019

| Make: | BMW | Model: | X5 | Body Style: | SUV |
|-------------|-------------------|---------------|-------------|----------------|-------------|
| Year: | 2008 | Registration: | KPA683 | Reg Expiry: | 03 Nov 2018 |
| WoF Expiry: | 08 May 2019 | Odometer: | 121,554 Kms | Good No: | 17765695 |
| VIN: | WBAFE42070LK94766 | Next Service: | 130000 | Service Histor | y: No |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

LR reflection broken

Exhaust need attention(left side misaligned)

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

RF suspension knocking noise

RF wheel bearing noisy

Excessive engine oil leaks

Cooling system need attention(dash warning light stay on and need further investigation)

Interior Comments Good Seats

| Carpets | Good |
|-----------|------|
| Panels | Good |
| Dashboard | Good |

General Comments

Driver AC vest broken Coolant condition fail

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

30 Jan 2019 Inspected by: **Bobby Zhong**

Name:

| | Pass | Fail | N/A |
|------------------------------|----------|---------|-----|
| Engine | • | | |
| Oil level | ~ | | |
| Smoke & fumes | ~ | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | • | | |
| Coolant condition | ~ | | |
| Performance | | ~ | |
| Radiator / Hoses (visual) | | ~ | |
| Transmission | | | • |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | | 1 | |
| Brakes | • | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | 2 | | mm |
| Right front | 2 | | mm |
| Left rear | 3 | 3 | mm |
| Right rear | 3 | | mm |
| Spare | | N/A | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | ~ | | |
| Electrical / Accessories | | | • |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | | 1 | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | ~ | | |
| Window winder RR | V | | |
| Rear view mirrors | ' | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 1 | | • |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | V |

Reversing camera

Signature: