

Report ID: 17,766,105 Version: 3 18 Mar 2019 Created:

Make:	BMW	Model:	5251	Body Style:	Sedan		Pass	Fail	N/A
Year:	2005	Registration:		Reg Expiry:	29 Jan 2020	Engine			
WoF Expiry:	05 Nov 2019	Odometer:	59,925 Kms	Good No:	17766105	Oil level	~		
VIN:	WBANA52010B57673(Service Histor		Smoke & fumes	~		
	WB/11/02010057075(Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	v		
						Performance	~		<u> </u>
Key:		-0			РТ	Radiator / Hoses (visual)	~		
S = scratch	Se	0		10/2	X	Transmission	V		
D = dent	scw dl			The	BID SPT	Operation	~		
R = rust				10	JHIH	Noise	~		
PT = paint defe C = crack	ect M			+		Clutch	V		
P = pin dent	Ho	KI			JIII —				~ ~
* = decals	s pip					CV joints Wheel bearings	~		
SC = stone chips							3		
W = significan	t scuffs	-	S	JUL		Brakes Performance	~		T
		Note: com		s may not be disr	laved in the diagram	Hand Brake	~ ~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							•		
Windscreen stone chips/2 remote keys and 1 plastic key						Tyres (lowest observed tread depth of tyres)			
						Left front	4		mm
						Right front	4	-	mm
						Left rear	•		mm
Conditions During Body Inspection: Dry						Right rear	4	4 mm	
Under Carriage & Under Bonnet Inspection Comments						Spare	N/A		
	mage & onder bor	<u>ince inspectie</u>	<u>n comments</u>			Suspension			1
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation V			
Good						Electrical / Accessories			T
Seats						Head lights	~		<u> </u>
Carpets	Good					Tail lights	~		
	Average					Indicators	~		<u> </u>
Panels	, we have					Dashboard warning lights	~		<u> </u>
Dashboa	rd Good					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		<u> </u>
Ganaral	Comments					Window winder FR	~		<u> </u>
						Window winder RL	~		<u> </u>
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		
L						Number of keys	3		
Road Conditions During Test Drive: Dry						Central locking	~		<u> </u>
Enging Ti	ning Mechanism	Timina	- Chain			Remote locking	~		<u> </u>
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	ог сапт вен керіас	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Ca Thach Date: 18 Mar 2019									

I have read and understood this condition guide.

Name:

Signature: