

Report ID: 17,766,146 Version: 3 08 Mar 2019 Created:

Make:	LDV	Model:	V80	Body Style:	Van		Pass	Fail	N/A
Year:	2017	Registration:	LCW627	Reg Expiry:	28 Dec 2018	Engine			<u> </u>
WoF Expiry:		Odometer:	22,122 Kms	Good No:	17766146	Oil level	~		
VIN:	LSKG5GL14HA075426	Next Service:	, -	Service Histor	<b>y:</b> No	Smoke & fumes	v		
						Performance	~		
	port is not a warranty		с I 1			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
		_				Performance	v		
Key:	S	-0	S S	-161-	s	Radiator / Hoses (visual)	~		
S = scratch	Re	A U			X.	Transmission	•		L
D = dent	sc			100		Operation	~		
R = rust PT = paint def				í In	JHIH	Noise	~		
C = crack					D	Clutch	•		~
P = pin dent						CV joints	~		-
* = decals	- MIK			- AL	EIR SD	Wheel bearings	~		
SC = stone chips						Brakes			L
W = significan	t scuffs	-			DW	Performance	~		
		Note: som	e defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							-		
Rear numberplate light missing LH sill damaged						Tyres (lowest observed tread depth of tyres)           Left front         1         mm			
	igea					Right front			mm
						Left rear		2	mm mm
Conditions During Body Inspection: Wet						Right rear	7 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
<u>onder ed</u>	inage a onder bor	ince inspectie	<u>eonnents</u>			Suspension Suspension performance			
							~		
						Steering performance Shock absorbers	~		
							•		
						Air Conditioning / Heater			<u> </u>
Interior Comments						Operation   Electrical / Accessories			
	Poor								<u> </u>
Seats						Head lights	~		-
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels	/ verage					Dashboard warning lights	~		<u> </u>
Dashboa	rd Average					Wipers (front & rear)	~		──
						Window winder FL	~		<u> </u>
General	omments					Window winder FR	~		
General Comments side trim needs attention						Window winder RL			~
side dimine						Window winder RR			~
						Rear view mirrors	~		<b> </b>
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)			~
						Number of keys	1		. <u> </u>
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		<u> </u>
Engine Ti	ming Mechanism	Timina	Chain			Remote locking	~		<u> </u>
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	or cam belt keplac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspecte	d by: Bobby Zhong					Date: 08 Mar 20	19		

I have read and understood this condition guide.

Name: .....

Signature: .....