



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	17,766,244
Version:	2
Created:	03 Aug 2019

Make:	Subaru	Body Style:	Sedan
Model:	WRX	VIN:	7AT0GF09X19003414
Year:	2011	Odometer:	60,668 Kms
Road Conditions During Test Drive:	Dry		

Electrical		Cooling System		Exterior	
1	Battery	30	Fuel Flap Release	78	Under Carriage
2	Headlights	31	Reversing Camera	79	Sun Roof Operation
3	Tail Lights	32	USB Port	80	Front Windscreen (no chips)
4	High Stop Light	33	Window Lock Switch	81	Back Windscreen (no chips)
5	Front Right Indicators	Transmission and Drive		82	Side Windows (no chips)
6	Front Left Indicators	34	Operation	83	Front Wiper Blades
7	Rear Right Indicators	35	Noise	84	Rear Wiper Blade
8	Rear Left Indicators	36	Clutch	85	R/H Mirror
9	Reversing Lights	37	CV Joints	86	L/H Mirror
10	Rear Reflectors	38	Wheel Bearing	87	L/F Guard
11	Hazard Lights	39	Wheel Balance	88	R/F Guard
12	Courtesy Lights	40	Gearbox (Manual)	89	L/H Doors
13	Dashboard Lights	41	Engine Timing	90	R/H Doors
14	Dashboard Dimmer Switch	42	Evidence of Cam Belt Replacement	91	L/H Sill
15	Number Plate Light	43	Replaced at (odometer reading)	92	R/H Sill
16	Dashboard Warning Lights	Brakes		93	Boot/Tail Gate
17	Speedo	44	Front Brakes	94	Front Bumper
18	Odometer	45	Rear Brakes	95	Rear Bumper
19	Rev Counter	46	Handbrake	96	Roof
20	Fuel Gauge	Keys and Locking		97	Bonnet
21	Wipers Front/Rear	47	Central Locking	98	Fuel Cap
22	Window Opener FL	48	Remote Locking	99	Mud Flaps
23	Window Opener FR	49	Number of Keys	100	WOF
24	Window Opener RL	Engine			
25	Window Opener RR	50	Oil Level		
26	Rear View Mirrors	51	Smokes and Fumes		
27	Radio (Basic Test Only)	52	Performance		
28	CD (Basic Test Only)	53	Noise		
29	Boot Open Switch	54	Starter Motor		
		Suspension			
		55	Coolant Condition		
		56	Performance		
		57	Radiator/Hoses (visual)		
		Wheels and Tyres			
		58	Suspension Performance		
		59	Steering Performance		
		60	Shock Absorbers		
		61	Left Front	5.0	mm
		62	Right Front	5.0	mm
		63	Left Rear	5.0	mm
		64	Right Rear	5.0	mm
		65	Spare	Yes	
		66	Tools		
		Interior			
		67	AC Operation		
		68	Heater Fan		
		69	Seatbelts		
		70	Horn		
		71	Seat Heaters		
		72	Sun Visors		
		73	Sun Visors Lights/Mirrors		
		74	Seats	Good	
		75	Carpets	Good	
		76	Panels	Good	
		77	Dashboard	Good	

Turners Certification Key:
 ✓ = Pass
 ✗ = Fail
 • = Not applicable for this vehicle

Inspected by:	Bobby Zhong	Date:	05 Feb 2019
I have read and understood this condition guide:			
Name:		Signature:	