

Basic Vehicle Condition Guide

Report ID: 17,766,445

Version: 1

Created: 19 Feb 2019


Make:BMWModel:3 SeriesBody Style:SedanYear:2009Registration:Reg Expiry:

 WoF Expiry:
 25 Jan 2020
 Odometer:
 62,299 Kms
 Good No:
 17766445

 VIN:
 WBAPG56080NL2068;
 Next Service:
 67263
 Service History:
 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Smoke from exhaust

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Bobby Zhong Date: 19 Feb 2019

Name:

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes		~		
Performance	~			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	~			
Clutch			~	
CV joints			~	
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread	d depth	of tyre	es)	
Left front		4	mm	
Right front		4	mm	
Left rear		4	mm	
Right rear		4	mm	
Spare		N/A		
Suspension				
Suspension performance	~			
Steering performance	\(\sigma \)			
Shock absorbers	~			
Air Conditioning / Heater			1	
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	V			
Dashboard warning lights	~			
Wipers (front & rear)	v v			
Window winder FL	~			
Window winder FR	~			
Window winder RL	~			
Window winder RR	~			
Rear view mirrors	~		+	
Radio (basic test only)	~			
CD (basic test only)	<i>v</i>			
Number of keys	2		1	
Central locking	.,			
Remote locking	1/			
			.,	
Sat. Nav. (basic test only)			.,	
Reversing camera				

Signature: