

Turners Certified Imports 50 Point Check

Report ID: 17,766,974

Version:

Turners Certified Key

X = Fail = Not applicable for this vehicle

Date: 18 Feb 2019

Signature:

= Pass

20 Mar 2019 Created:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA

IMPORTED VEHICLES accredi	ted inspection agency and been to	est driven up to 50km/h from cold.	
		Seats: Good Carpets: Good Panels: Good Dashboard: Good Engine Timing Mechanism: Evidence of Cam Belt Replacement:	Timing Chain Not Applicable
		Replaced At (odometer reading): Road Conditions During Test Drive:	Wet
Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)
Battery	Operation	Oil level	Left front 4.0 mm
Head lights	Noise	Smoke & fumes	Right front 4.0 mm
Tail lights	Clutch	Performance	Left rear 4.5
Indicators	CV joints	Noise	Right rear 4.5 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear)	Wheel balance	Coolant condition	Tools
Window winder FL	Brakes	Performance	Interior
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RL	Hand Brake	nadiator / rioses (visual)	Heater fan
Window winder RR	Tidita branc	Suspension	Seatbelts
Rear view mirrors	Keys & Locking	Suspension performance	Horn
Radio (basic test only)	Central locking	Steering performance	Tiom

Shock absorbers

Inspected by: Xinghui Lin

1

•

Remote locking

Number of keys

CD (basic test only)

Reversing camera