


|                    |                  |                      |             |                         |             |
|--------------------|------------------|----------------------|-------------|-------------------------|-------------|
| <b>Make:</b>       | Hyundai          | <b>Model:</b>        | Iload       | <b>Body Style:</b>      | Van         |
| <b>Year:</b>       | 2017             | <b>Registration:</b> | KRT400      | <b>Reg Expiry:</b>      | 30 Sep 2019 |
| <b>WoF Expiry:</b> | 14 Jul 2020      | <b>Odometer:</b>     | 104,305 Kms | <b>Good No:</b>         | 17766988    |
| <b>VIN:</b>        | KMFWBX7KLHU91626 | <b>Next Service:</b> |             | <b>Service History:</b> | Yes         |

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**

S = scratch  
D = dent  
R = rust  
PT = paint defect  
C = crack  
P = pin dent  
\* = decals  
SC = stone chips  
W = significant scuffs


**Body Inspection Comments**

Rear bumper misaligned

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Wet

**Under Carriage & Under Bonnet Inspection Comments**

Rear wheel drive

**Interior Comments**

|           |         |
|-----------|---------|
| Seats     | Good    |
| Carpets   | Average |
| Panels    | Average |
| Dashboard | Good    |

**General Comments**

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

|   | Pass | Fail | N/A |
|---|------|------|-----|
| <b>Engine</b>                                       |      |      |     |
| Oil level   | ✓    |      |     |
| Smoke & fumes                                       | ✓    |      |     |
| Performance   | ✓    |      |     |
| Noise   | ✓    |      |     |
| <b>Cooling System</b>                               |      |      |     |
| Coolant condition                                   | ✓    |      |     |
| Performance   | ✓    |      |     |
| Radiator / Hoses (visual)                           | ✓    |      |     |
| <b>Transmission</b>                                 |      |      |     |
| Operation   | ✓    |      |     |
| Noise   | ✓    |      |     |
| Clutch  | ✓    |      |     |
| CV joints   |      |      | ✓   |
| Wheel bearings                                      | ✓    |      |     |
| <b>Brakes</b>                                       |      |      |     |
| Performance   | ✓    |      |     |
| Hand Brake  | ✓    |      |     |
| <b>Tyres</b> (lowest observed tread depth of tyres) |      |      |     |
| Left front  | 3    | mm   |     |
| Right front   | 3    | mm   |     |
| Left rear   | 3.5  | mm   |     |
| Right rear  | 3.5  | mm   |     |
| Spare   | Yes  |      |     |
| <b>Suspension</b>                                   |      |      |     |
| Suspension performance                              | ✓    |      |     |
| Steering performance                                | ✓    |      |     |
| Shock absorbers                                     | ✓    |      |     |
| <b>Air Conditioning / Heater</b>                    |      |      |     |
| Operation   | ✓    |      |     |
| <b>Electrical / Accessories</b>                     |      |      |     |
| Head lights   | ✓    |      |     |
| Tail lights   | ✓    |      |     |
| Indicators  | ✓    |      |     |
| Dashboard warning lights                            | ✓    |      |     |
| Wipers (front & rear)                               | ✓    |      |     |
| Window winder FL                                    | ✓    |      |     |
| Window winder FR                                    | ✓    |      |     |
| Window winder RL                                    |      |      | ✓   |
| Window winder RR                                    |      |      | ✓   |
| Rear view mirrors                                   | ✓    |      |     |
| Radio (basic test only)                             | ✓    |      |     |
| CD (basic test only)                                |      |      | ✓   |
| Number of keys                                      | 2    |      |     |
| Central locking                                     | ✓    |      |     |
| Remote locking                                      | ✓    |      |     |
| Sat. Nav. (basic test only)                         |      |      | ✓   |
| Reversing camera                                    | ✓    |      |     |

Inspected by: Bobby Zhong

Date: 24 Jul 2019

I have read and understood this condition guide.

Name: .....

Signature: .....