

## **Turners Certified Imports 50 Point Check**

Report ID: 17,767,694

Version:

05 Mar 2019 Created:


## **Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make: Toyota **Body Style: Wagon** Good Seats: Odometer: 124,816 Kms Estima Model: Good Carpets: 7AT0H61YX19013515 2005 VIN: Year: Good Panels: **Under Carriage & Under Bonnet Inspection Comments** Dashboard: Good Timing Chain **Engine Timing Mechanism:** Not Applicable **General Comments Evidence of Cam Belt Replacement:** Replaced At (odometer reading): Dry **Road Conditions During Test Drive: Electrical Transmission & Drive Engine** depth) **Battery** Operation Oil level Left front







Inspected by: Mathew Varghese



Reversing camera

Date: 05 Mar 2019