

Turners Certified Imports 50 Point Check

Report ID: 17,768,697

Version: 1

21 Mar 2019 Created:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make: Toyota **Body Style: Minibus** Odometer: 99,205 Kms Hiace Model: 2016 7AT0H60FX19044195 VIN:

Under Carriage & Under Bonnet Inspection Comments

General Comments

10 seater

Year:

Good Seats: Good Carpets: Good Panels: Dashboard: Good

Timing Chain **Engine Timing Mechanism:** Not Applicable **Evidence of Cam Belt Replacement:**

Replaced At (odometer reading):

Road Conditions During Test Drive:

Dry

Electrical Battery Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Reversing camera •





