

Turners Certified Imports 50 Point Check

Report ID: 17,769,000

Version: 1

28 Mar 2019 Created:

Note: This report is not a warranty


This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.


Nissan Make: **Body Style: SUV** Seats: X-Trail Odometer: 113,727 Kms Model: 7AT0DH6LX19002252 2008 VIN: Year: Panels: **Under Carriage & Under Bonnet Inspection Comments General Comments**


Good Good Carpets: Good Dashboard: Good

Timing Chain **Engine Timing Mechanism:** Not Applicable **Evidence of Cam Belt Replacement:** Replaced At (odometer reading): Dry **Road Conditions During Test Drive:**









Inspected by: Sudhin Ramachandran Date: 26 Mar 2019