

Report ID: 17,769,282 Version: 1 28 Mar 2019 Created:

Make:	Suzuki	Model:	Swift	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2011		HGZ578	Reg Expiry:	17 Apr 2019	Engine	1 435	1 011	
WoF Expiry:		Odometer:	HGZ 578 98,785 Kms	Reg Expiry: Good No:	17 Apr 2019 17769282	Oil level			<u> </u>
								~	<u> </u>
VIN:	7AT0GK0CX13129824	Next Service:	80,000	Service Histor	y: No	Smoke & fumes	~		<u> </u>
Note: This re	port is not a warranty					Performance	~		<u> </u>
	a guide only. Conside					Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
		•	5		J	Coolant condition	~		
Kow	S D PT	$\sim$	PT PT P			Performance	~		
<b>Key:</b> S = scratch		$\sim$		5(O)7		Radiator / Hoses (visual)	~		
						Transmission			
R = rust				10		Operation	~		
PT = paint def	ect NP					Noise	~		
C = crack						Clutch			~
P = pin dent	HIP				7414	CV joints	~		
* = decals	s glg			10	FID SD	Wheel bearings	V		
SC = stone chips						Brakes			
W = significant scuffs W S S P SC						Performance	~		
Da alta La		Note: som	ne defects & blemishes	s may not be disc	layed in the diagram	Hand Brake	~		+
body inspection comments						Tyres (lowest observed tread depth of tyres)			 >s)
Brake lights, front park lights, number plate lights not working Rear bumper misaligned. RL wheel cap missing						Left front		,	 
Bonnet stay rod insecure						Right front			mm
						Left rear	6		mm
Conditions During Body Inspection: Dry						Right rear	4 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
					Suspension			·	
Front brake Engine oil t						Suspension performance		~	<u> </u>
<u> </u>						Steering performance	~		<u> </u>
						Shock absorbers		~	
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Average			Wipers (front & rear)	~				
Dashboa	rd					Window winder FL	~		
	1					Window winder FR	~		1
General Comments					Window winder RL	~		<u> </u>	
Front and rear suspension bouncing					Window winder RR	~		<u> </u>	
Steering knocking noise Engine rattling noose in slow drive						Rear view mirrors	~		
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		<u> </u>
						Number of keys	1		L
		Duite				Central locking	· ·		
Koad Con	ditions During Test	Urive:	Dry			3			
Engine Timing Mechanism: Timing Chain						Remote locking	~		<u> </u>
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
LUNGINE				11115.		Reversing camera			~
Inspected by: Mathew Varghese						Date: 28 Mar 2019			
inspecte						Bate. 20 mai 20	-		
I have read	and understood th	is condition q	juide. Name:			Signature:			