

Report ID: 17,769,796 Version: 4 Created: 01 Aug 2019

Make:	Nissan	Model:	Navara	Body Style:	Utility		Pass	Fail	N/A
Year:	2012	Registration:	LYY827	Reg Expiry:	30 Jan 2020	Engine	1	i	1
WoF Expiry:	16 Jul 2020	Odometer:	110,857 Kms	Good No:	17769796	Oil level	~		
VIN:	VSKCVND40A0475758	Next Service:		Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and tr	his can be arranged to	or an additional of	narge.	Coolant condition	~		
	S D S		S P S SC		S	Performance	~		
Key:	130 []3	=		5(0)-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
R = rust	SDCW			10	Ell s	Operation	~		
PT = paint def	ect NP	1				Noise	~		
C = crack						Clutch	~		
P = pin dent	sc de				74HL	CV joints	~		
* = decals		10		10	E S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	SC S		S S	W	S	Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
Front bumper misaligned						Tyres (lowest observed tread depth of tyres)			
FR and rear seats worn Stone chips on the windscreen						Left front	6	5	mm
Stone chips	son the windscreen					Right front	5	.5	mm
						Left rear	5	5	mm
Conditions During Body Inspection: Dry						Right rear	5.5 m		mm
Under Carriage & Under Bonnet Inspection Comments					Spare Yes				
	rriage & Under Bor	net Inspectio	on Comments			Suspension			
4WD Underbody	surface rust					Suspension performance	~		
Left sill dent						Steering performance	~		
Underbody cover dent Engine oil leak (minor)						Shock absorbers	~		
						Air Conditioning / Heater			
Interior C	ommonts					Operation	~		
Interior Comments						Electrical / Accessories			
Seats	1001					Head lights	~		
Carpets	Average					Tail lights	~		ļ
	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		ļ!
Dashboa	Average					Wipers (front & rear)	~		
						Window winder FL	~		<u> </u>
Conorol	- one on to					Window winder FR	~		<u> </u>
	<u>Comments</u>					Window winder RL	~		<u> </u>
Clutch pedal Spring noisy Canopy key missing					Window winder RR	~		<u> </u>	
Engine whi	ning noise					Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		
L						Number of keys	1		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		<u> </u>
Engine Ti	ming Machanism	Cambel	F			Remote locking	~		<u> </u>
						Sat. Nav. (basic test only)			~
Evidence	ог сапт вен керіас	ement: N	lo	Kms:		Reversing camera			~
Inspecte	d by: Sudhin Ramach	andran				Date: 01 Aug 20	19		
	•					J			

I have read and understood this condition guide.

Name:

Signature: