

Conditions During Body Inspection:	Dry
------------------------------------	-----

Under Carriage & Under Bonnet Inspection Comments

				Shock absorbers	~		
				Air Conditioning / Heater			
				Operation	~		
Interior Comme	Interior Comments			Electrical / Accessories			
Seats	Good			Head lights	~		
	Good			Tail lights	~		
Carpets				Indicators	~		
Panels	Good			Dashboard warning lights	~		
	Good			Wipers (front & rear)	~		
Dashboard				Window winder FL	~		
				Window winder FR	~		
General Comm	<u>ents</u>			Window winder RL		~	
				Window winder RR		~	
				Rear view mirrors	~		
				Radio (basic test only)	~		
				CD (basic test only)	~		
				Number of keys	2		
Road Condition	Road Conditions During Test Drive: Dry			Central locking	~		
				Remote locking	~		
Engine Timing Mechanism: Cambelt				Sat. Nav. (basic test only)		~	
Evidence of Can	n Belt Replacement: Yes	Kms: 1	83,000	Reversing camera		~	
Inspected by:	lan Dunn			Date: 19 Jun 201	19		

I have read and understood this condition guide.

Name:

Signature:

1

Pass

V

V

V

V

V

V

V

V

V

V

~

~

7.2

7.2

6.3

6.2

V

v

Yes

Spare

Suspension

Suspension performance

Steering performance

20 Jun 2019

Fail

N/A

V

~

mm

mm

mm

mm