

Basic Vehicle Condition Guide

Report ID: 17,773,485


Version: 2

Created: 04 Sep 2019

Make: Model: Toyota **Avensis Body Style:** Wagon Year: 2015 Registration: JJY755 Reg Expiry: 28 Sep 2019 WoF Expiry: **Odometer:** 01 Sep 2020 82,526 Kms **Good No:** 17773485 VIN: SB1EK76L30E041112 Next Service: 73,500 **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

No spear wheel has puncher repair kit Front windscreen stone chips

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Brake rotors warn pads low

Interior Comment	<u>s</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

31 Aug 2019 Inspected by: lan Dunn Date:

Name:

Pass	Fail	N1/A
	-	N/A
~		
~		
~		
~		
	•	
~		
~		
~		
	•	•
~		
~		
		~
~		
~		
•		
~		
~		
d depth	of tyre	es)
3	.2	mm
3.7		mm
5	.1	mm
5.9		
	.9	mm
	.9 No	mm
		mm
5		mm
5		mm
		mm
5		mm
5 V V V V		mm
5 V V V V		mm
5 V V V V		mm
> V V V V V V V V V V V V V V V V V V V		mm
> V V V V V V V V V V V V V V V V V V V		mm
> V V V V V V V V V V V V V V V V V V V		mm
> V V V V V V V V V V V V V V V V V V V		mm
> V V V V V V V V V V V V V V V V V V V		mm
5 V V V V		mm
V		mm
ママママママママママママママママママママママママママママママママママママ		
ママママママママママママママママママママママママママママママママママママ		mm
ファイン ママ		mm
ファイン ママ		mm
ファイン ママ		
	/ / / / / / / / / / / / / / / / / / /	v v v v depth of tyre 3.2 3.7

Signature: