

Report ID: 17,774,012 Version: 1 Created: 16 Sep 2019

Make:	Holden	Model:	Colorado	Body Style:	Utility] [Pass	Fail	N/A	
Year:	2016	Registration:	KBK264	Reg Expiry:	05 Dec 2019	Engine	1	i	1	
WoF Expiry:	13 Sep 2020	Odometer:	117,838 Kms	Good No:	17774012	Oil level	~			
VIN:	MMU148EK0GH64766	Next Service:	118,000	Service Histor	y: Yes	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	aration is made	for ago and miloago	Parts have not	been dismonthed or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~		1	
						Performance	~			
Key:	S SC	-0	S D SC	-01-	S SC	Radiator / Hoses (visual)	~			
S = scratch						Transmission			1	
D = dent	S SC			715	HIL	Operation	~			
R = rust PT = paint defect						Noise	~			
						Clutch			~	
P = pin dent	HID				게	CV joints			~	
* = decals	s sc glg			-No-	SPSC	Wheel bearings	~			
SC = stone chips						Brakes	Brakes			
W = significant scuffs S SC SC SC SC						Performance	~			
Podulac		Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~			
body inspection comments						Tyres (lowest observed tread	Tyres (lowest observed tread depth of t			
Front windscreen stone chips									mm	
						Right front	7		mm	
						Left rear	7		mm	
Condition	ns During Body Insi	nection:	Dry			Right rear		.3	mm	
Conditions During Body Inspection: Dry						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation 🖌				
Interior Comments						Electrical / Accessories			<u> </u>	
Seats	Good					Head lights	~			
	Good					Tail lights	~		-	
Carpets	Good					Indicators	~			
Panels	Good					Dashboard warning lights	~			
<u></u>	, Good					Wipers (front & rear)	~			
Dashboa	rd					Window winder FL	~			
						Window winder FR	~			
General Comments						Window winder RL	~		1	
						Window winder RR	~		1	
						Rear view mirrors	~		1	
						Radio (basic test only)	~			
						CD (basic test only)			~	
						Number of keys	2			
Road Conditions During Test Drive: Dry						Central locking	~			
,						Remote locking	~			
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: No Kms:						Reversing camera		-	~	
Inspected	d by: lan Dunn					Date: 16 Sep 20	19			

I have read and understood this condition guide.

Name:

Signature: