

 Report ID:
 17,775,315

 Version:
 1

 Created:
 24 Oct 2019

Make:	Toyota	Model:	Hilux	Body Style:	Utility		Pass	Fail	N/A	
Year:	2014	Registration:		Reg Expiry:	28 Jan 2020	Engine				
WoF Expiry:		Odometer:	261,278 Kms	Good No:	17775315	Oil level	~			
VIN:	MR0FZ22GX01200420	Next Service:		Service Histor		Smoke & fumes	~			
			,		•	Performance	~			
	port is not a warranty		с I I			Noise	~			
diagnostic te	a guide only. Conside sting undertaken. The	vehicle has beer	n driven up to 50km/h	from cold. The	Vendor recommends	Cooling System	•			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional	charge.	Coolant condition	~			
						Performance	~			
Key:		-0				Radiator / Hoses (visual)	~			
S = scratch	STE	A CO			The	Transmission	•			
D = dent	6/6			10-		Operation	~			
R = rust PT = paint defe				$\prod$	JHIH	Noise	~			
C = crack						Clutch	~			
P = pin dent						CV joints	~			
* = decals	616				EIIP I	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs						Performance	~			
		Note: son	ne defects & blemishes	may not be disi	played in the diagram	Hand Brake	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	•	of tyre	 (ک	
Front driving lights caps missing									 	
						Right front		.3	mm	
						Left rear		.5	mm	
Condition	os During Body Ins	noction:	Wet			Right rear		.3	mm	
Conditions During Body Inspection: Wet						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
	Good					Tail lights	~			
Carpets	Good					Indicators	~			
Panels	Good					Dashboard warning lights	v			
						Wipers (front & rear)	~		-	
Dashboa	ord Good					Window winder FL	~			
	1					Window winder FR	~			
General Comments						Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	3	I	I	
Road Conditions During Test Drive: Dry						Central locking	V			
						Remote locking	~			
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera	~			
Inspected by: Ian Dunn Date: 24 Oct 2019										

I have read and understood this condition guide.

Name: .....

Signature: .....