

Report ID: 17,776,177 Version: 2 30 Nov 2018 Created:

Make:MitsubishiModel:OutlanderBody Style:SUVYear:2015Registration:HWP14Reg Expiry:14 Jan 2019WoF Expiry:30 Nov 2019Odometer:114,147 KmsGood No:17776177VIN:JMFXLGF6WEZ002065Next Service:122000Service History:NoNote: This report is not a warrantyThis report is not a warrantySmoke & fumesThis report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.PerformanceKey:SPSDPSSS = scratchSDPSRadiator / Hoses (visual TransmissionPerformance		Fail N/A
WoF Expiry: 30 Nov 2019       Odometer: 114,147 Kms       Good No: 17776177         VIN: JMFXLGF6WEZ002065       Next Service: 122000       Service History: No         Note: This report is not a warranty       This report is not a warranty         This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.       Performance         Key:       SP       SDP       S         S = scratch       SP       SDP       S		
VIN:       JMFXLGF6WEZ002065       Next Service:       122000       Service History:       No       Smoke & fumes         Note: This report is not a warranty       This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.       Smoke & fumes       Performance         Key:       SP       SDP       S       S       Radiator / Hoses (visual Transmission		
Note: This report is not a warranty         This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.       Performance         Key:       SP       SDP       S         S = scratch       SP       SDP       S		
Note: This report is not a warranty         This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or         diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends         a full mechanical inspection prior to purchase and this can be arranged for an additional charge.         Key:         S = scratch		
Key:       S P       S D P       S       S       S       Radiator / Hoses (visual Transmission	<b>v</b> <b>v</b>	
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.       Coolant condition         Key:       S P       S D P       S         S = scratch       Radiator / Hoses (visual Transmission	· ·	-
Key:     S P     S D P     S     Performance       S = scratch     Radiator / Hoses (visual     Transmission	· ·	
Key:     S P     S D P     S     Radiator / Hoses (visual Transmission       S = scratch     Transmission	-	
S = scratch		
	~	
D = dent S Operation		
R=rust	~	
PT = paint defect	~	
C = crack P = pin dent C/ ioints		~
*= decals	~	
SC = stone chips Wheel bearings	~	
W = significant scuffs S D W S D Brakes		
	~	
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram Hand Brake	~	
Scratch marks both taillight lens .Stone chips front screen.	ead depth c	of tyres)
Left front	5.0	mm
Right front	5.0	mm
Left rear	6.0	mm
Conditions During Body Inspection: Dry Right rear	6.0	mm
Spare		Yes
Under Carriage & Under Bonnet Inspection Comments Suspension		
Suspension performance	e 🖌	
Steering performance	~	
Shock absorbers	~	
Air Conditioning / Heat	er	
Operation	~	
Interior Comments Electrical / Accessories	I	
Seats *Good n Drivers seat sign of wear. Head lights	~	
Tail lights	~	
Carpets Indicators	~	
Panels         Good n left front door trim scratched.         Dashboard warning ligition	its 🖌	
Wipers (front & rear)	~	
Dashboard Window winder FL	~	
Window winder FR	· ·	
General Comments Window winder RL	~	
Road noise from tyres. Window winder RR	· ·	
Rear view mirrors	~	
Radio (basic test only)	~	
CD (basic test only)	v	
Number of keys	2	I
	· ·	
Road Conditions During Test Drive:     Dry     Central locking       Remote locking     Remote locking	· ·	
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test onl		· ·
Evidence of Cam Belt Replacement: Not Applicable Kms: Reversing camera	) //	
Inspected by: Eddie Marsters Date: 14 Nov	2018	

I have read and understood this condition guide.

Name: .....

Signature: .....