

Basic Vehicle Condition Guide

Report ID: 17,777,072


Version: 1

Created: 13 Dec 2018

Make: Model: Mazda CX-9 **Body Style:** SUV Year: 2015 Registration: JLK579 Reg Expiry: 08 Nov 2019 Good No: WoF Expiry: **Odometer:** 11 Dec 2019 87,151 Kms 17777072 VIN: JM0TB10A5G0440565 Next Service: 88000 **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chips front screen. Scratch marks left hand taillight lens. Spider marks on roof

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Engine oil level on low mark.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

13 Dec 2018 Inspected by: **Eddie Marsters**

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	\(\times \)		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	<i>V</i>		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed treac	l denth	of tyre	25)
Left front	I	3	mm
Right front		3 3	mm
Left rear			mm
Right rear	7		mm
Spare		Yes	
Suspension		103	
Suspension performance	V		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	V		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators			
Dashboard warning lights	v v		
Wipers (front & rear)	<i>v</i>		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	V		
CD (basic test only)	~		
Number of keys	2		
Central locking	·		
Remote locking	V		
Sat. Nav. (basic test only)	V		
Reversing camera	<i>v</i>		
eversing cumera			1

Signature: